



Butte Incident

Photo 1

9/9/2015 5:17 PM

Facing west looking at the General Origin Area.



Butte Incident

Photo 2

9/9/2015

5:17 PM

Facing southwest looking at the General Origin Area.



Butte Incident

Photo 3

9/9/2015 5:19 PM

Facing south looking at the General Origin Area.



Butte Incident

Photo 4

9/9/2015 5:19 PM

Facing south looking at the General Origin Area.



Butte Incident

Photo 5

9/9/2015 5:19 PM

Facing east looking at the General Origin Area from below the powerlines.



Butte Incident

Photo 6

9/9/2015 5:20 PM

Facing northeast looking at the General Origin Area.



Butte Incident

Photo 7

9/9/2015 5:20 PM

Facing north looking at the General Origin Area.



Butte Incident

Photo 8

9/9/2015 5:20 PM

Facing north looking at the General Origin Area.



Butte Incident

Photo 9

9/9/2015 6:04 PM

Facing west, looking at Grey pine (Evidence Item 1) laying within the General Origin Area below the powerline conductors.



Butte Incident

Photo 10

9/9/2015 6:04 PM

Top portion of Grey pine (Evidence Item 1) laying within the General Origin Area.



Butte Incident

Photo 11

9/9/2015 6:04 PM

Close up of Grey pine (Evidence Item 1) showing top portion of tree is unburned except for two small branches and stem of the tree that contacted the powerline conductor.



Butte Incident

Photo 12

9/9/2015 6:05 PM

Evidence Item 1: Close up of burned stem with pitch (sap) bubbles and the burned tips of two branches.



Butte Incident

Photo 13

9/11/2015 7:57 AM

Evidence Item 1: Cut into sections for collection as evidence.



Butte Incident

Photo 14

9/11/2015 7:58 AM

Evidence Item 1: Each cut was numerically marked.



Butte Incident

Photo 15

9/11/2015 7:58 AM

The base (stump) of Evidence Item 1.



Butte Incident

Photo 16

9/11/2015 12:35 PM

Overhead powerlines above the Specific Origin Area.



Butte Incident

Photo 17

9/11/2015 12:39 PM

Facing south, view of the powerline conductors over the Specific Origin Area from Trees Inc. bucket truck. Discoloration is visible on the northern (closest) conductor.



Butte Incident

Photo 18

9/11/2015 12:39 PM

Facing south, view of discoloration on northern most powerline conductor over the Specific Origin Area.



Butte Incident

Photo 19

9/11/2015 12:40 PM

Facing south, looking at additional discoloration on northern most powerline conductor over the Specific Origin Area.



Butte Incident

Photo 20

9/11/2015 12:41 PM

Facing south, looking at discoloration on northern most powerline conductor over the Specific Origin Area.



Butte Incident

Photo 21

9/13/2015 1:58 PM

Remaining base (stump) of Evidence Item 1.



Butte Incident

Photo 22

9/13/2015 1:58 PM

Close up of the base (stump) of Evidence Item 1.



Butte Incident

Photo 23

9/13/2015 1:58 PM

Base (stump) of Evidence Item 1.



Butte Incident

Photo 24

9/13/2015 2:01 PM

Compass was used to identify North and a black sharpie used to mark "N" and "S" on the base (stump) of Evidence Item 1.



Butte Incident

Photo 25

9/13/2015 2:02 PM

Close up of the base of Evidence Item 1 showing the North and South marked on the base.



Butte Incident

Photo 26

9/13/2015 2:06 PM

Evidence Item 2.



Butte Incident

Photo 27

9/13/2015 2:06 PM

Close up of the top of Evidence Item 2.



Butte Incident

Photo 28

9/13/2015 2:07 PM

Close up of the bottom of Evidence Item 2.



Butte Incident

Photo 29

9/13/2015 2:50 PM

Facing east, looking at PG&E vehicle moved into the Specific Origin Area for collection of powerline conductor.



Butte Incident

Photo 30

9/13/2015 2:50 PM

Facing east, looking at PG&E vehicle moved into the Specific Origin Area for collection of powerline conductor.



Butte Incident

Photo 31

9/13/2015 2:50 PM

Facing east, looking at powerline conductors over the General Origin Area of the fire.



Butte Incident

Photo 32

9/13/2015 3:42 PM

From PG&E bucket truck, facing south, looking at powerline conductors over the Specific Origin Area.



Butte Incident

Photo 33

9/13/2015 3:43 PM

From PG&E bucket truck, facing south, looking at powerline conductors over the Specific Origin Area.



Butte Incident

Photo 34

9/13/2015 3:43 PM

From PG&E bucket truck, facing south, looking at powerline conductors over the Specific Origin Area.



Butte Incident

Photo 35

9/13/2015 3:44 PM

Facing southwest, looking at the start of the discoloration on the northern (closest) most conductor. (Discoloration visible on left side of photo)



Butte Incident

Photo 36

9/13/2015 3:44 PM

Facing southeast, view of discoloration on the northern (closest) most conductor.



Butte Incident

Photo 37

9/13/2015 3:46 PM

Close up of northern most powerline conductor showing discoloration on the left side of the photo.



Butte Incident

Photo 38

9/13/2015 3:46 PM

Close up of northern most powerline conductor, view of discoloration, moving east along conductor from photo 37.



Butte Incident

Photo 39

9/13/2015 3:46 PM

Continuing east along conductor, close up of northern most powerline conductor over the Specific Origin Area showing discoloration.



Butte Incident

Photo 40

9/13/2015 3:46 PM

Continuing east along conductor, close up of northern most powerline conductor over the Specific Origin Area showing discoloration.



Butte Incident

Photo 41

9/13/2015 3:46 PM

Continuing east along conductor, close up of northern most powerline conductor over the Specific Origin Area showing discoloration.



Butte Incident

Photo 42

9/13/2015 3:46 PM

Continuing east along conductor, close up of northern most powerline conductor over the Specific Origin Area showing discoloration.



Butte Incident

Photo 43

9/13/2015 3:46 PM

Continuing east along conductor, close up of northern most powerline conductor over the Specific Origin Area showing discoloration.



Butte Incident

Photo 44

9/13/2015 3:46 PM

Continuing east along conductor, close up of northern most powerline conductor over the Specific Origin Area showing discoloration.



Butte Incident

Photo 45

9/13/2015 3:46 PM

Continuing east along conductor, close up of northern most powerline conductor over the Specific Origin Area showing discoloration.



Butte Incident

Photo 46

9/13/2015 3:46 PM

Blurred photo of the powerline conductor.



Butte Incident

Photo 47

9/13/2015 3:48 PM

Overhead view of the remaining base (stump) of Evidence Item 1 and trees surrounding it on the north side.



Butte Incident

Photo 48

9/13/2015 3:48 PM

View of trees surrounding Evidence Item 1, moving up the stems from the previous photo.



Butte Incident

Photo 49

9/13/2015 3:48 PM

View of trees surrounding Evidence Item 1, continuing to show view moving up the trees.



Butte Incident

Photo 50

9/13/2015 3:48 PM

View of trees surrounding Evidence Item 1, continuing to show view moving up the trees.



Butte Incident

Photo 51

9/13/2015 3:48 PM

View of trees surrounding Evidence Item 1, continuing to show view moving up the trees.



Butte Incident

Photo 52

9/13/2015 3:48 PM

View of trees surrounding Evidence Item 1, continuing to show view moving up the trees.



Butte Incident

Photo 53

9/13/2015 3:48 PM

View of trees surrounding Evidence Item 1, continuing to show view moving up the trees.



Butte Incident

Photo 54

9/13/2015 3:49 PM

Facing west from the Specific Origin Area, view of powerlines from the PG&E bucket truck.



Butte Incident

Photo 55

9/13/2015 3:49 PM

Facing east from the Specific Origin Area, view of the powerlines from the PG&E bucket truck.



Butte Incident

Photo 56

9/13/2015 3:50 PM

View of the center powerline conductor within the Specific Origin Area.
No discoloration visible on the conductor.



Butte Incident

Photo 57

9/13/2015 3:50 PM

View of the southern most powerline conductor within the General Origin Area. No discoloration visible on the conductor.



Butte Incident

Photo 58

9/13/2015 3:52 PM

From the PG&E bucket truck, facing east, view of the powerlines from the Specific Origin Area towards Charamuga Ranch Road.



Butte Incident

Photo 59

9/13/2015 3:52 PM

View of powerlines continuing east across Charamuga Ranch Road.



Butte Incident

Photo 60

9/13/2015 3:52 PM

View of powerlines continuing east across Charamuga Ranch Road.



Butte Incident

Photo 61

9/13/2015 4:46 PM

PG&E crew removing section of northern most powerline conductor over the SOA, Evidence Item #3.



Butte Incident

Photo 62

9/13/2015 4:51 PM

PG&E crew removing section of northern most powerline conductor over the SOA, Evidence Item #3.



Butte Incident

Photo 63

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east.




Butte Incident

Photo 64

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east.




Butte Incident

Photo 65

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 66

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 67

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 68

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 69

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 70

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 71

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 72

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 73

9/13/2015 5:04 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 74

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 75

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 76

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 77

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 78

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.




Butte Incident

Photo 79

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 80

9/13/2015 5:0 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 81

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 82

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 83

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east.



Butte Incident

Photo 84

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item moving east. Discoloration visible on conductor.



Butte Incident

Photo 85

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 86

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 87

9/13/2015 5:05 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 88

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 89

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 90

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 91

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 92

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 93

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 94

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 95

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.




Butte Incident

Photo 96

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 97

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 98

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.




Butte Incident

Photo 99

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.




Butte Incident

Photo 100

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 101

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 102

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 103

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 104

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 105

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 106

9/13/2015 5:06 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from east end of item to the west after conductor was rolled to view other side. Close up of discoloration visible on the conductor.



Butte Incident

Photo 107

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 108

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.




Butte Incident

Photo 109

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.




Butte Incident

Photo 110

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.




Butte Incident

Photo 111

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 112

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 113

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.




Butte Incident

Photo 114

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 115

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 116

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 117

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 118

9/13/2015 5:07 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 119

9/13/2015 5:08 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 120

9/13/2015 5:08 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 121

9/13/2015 5:08 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.




Butte Incident

Photo 122

9/13/2015 5:08 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 123

9/13/2015 5:08 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.



Butte Incident

Photo 124

9/13/2015 5:08 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side. Discoloration visible on the conductor.




Butte Incident

Photo 125

9/13/2015 5:08 PM

Close up of powerline conductor (Evidence Item 3). Series of photos starting from west end of item to the east after conductor was rolled to view other side.



Butte Incident

Photo 126

9/13/2015 5:08 PM

Close up of powerline conductor (Evidence Item 3). Close up of a portion of the discolored area showing substance stuck to the conductor.



Butte Incident

Photo 127

9/13/2015 5:08 PM

Close up of powerline conductor (Evidence Item 3). Close up of a portion of the discoloration in the area where it appears a substance is stuck to the conductor.



Butte Incident

Photo 128

9/13/2015 5:08 PM

Close up of powerline conductor (Evidence Item 3). Close up of a portion of the discoloration in the area where it appears a substance is stuck to the conductor.



Butte Incident

Photo 129

9/13/2015 5:09 PM

Overview of Evidence Item 3.



Butte Incident

Photo 130

9/13/2015 5:20 PM

Evidence Item 3 being packaged as evidence.



Butte Incident

Photo 131

9/16/2015 11:19 AM

Taken from helicopter, facing south, view of the origin area.



Butte Incident

Photo 132

9/16/2015 11:20 AM

Taken from helicopter, facing south, view of the origin area



Butte Incident

Photo 133

9/16/2015 11:20 AM

Taken from helicopter, facing south to southeast, view of the origin area



Butte Incident

Photo 134

9/16/2015 11:20 AM

Taken from helicopter, facing south to southeast, view of the origin area and residence at the end of Charamuga Ranch Road.



Butte Incident

Photo 135

9/16/2015 11:20 AM

Taken from helicopter, facing south to southeast, view of the origin area and residence at the end of Charamuga Ranch Road.



Butte Incident

Photo 136

9/16/2015 11:20 AM

Taken from helicopter, facing south to southeast, closer view of the origin area and powerline corridor.



Butte Incident

Photo 137

9/16/2015 11:20 AM

Taken from helicopter, facing east to southeast, overview of the powerline corridor and origin area.



Butte Incident

Photo 138

9/16/2015 11:20 AM

Taken from helicopter, facing east, looking down the powerline corridor at the origin area.



Butte Incident

Photo 139

9/16/2015 11:20 AM

Taken from helicopter, facing east, looking down the powerline corridor with a closer view of the origin area.



Butte Incident

Photo 140

9/16/2015 11:21 AM

Taken from helicopter, facing east to northeast, looking back at the powerline corridor and the origin area.



Butte Incident

Photo 141

9/16/2015 11:21 AM

Taken from helicopter, facing northeast, looking back at the origin area.



Butte Incident

Photo 142

9/16/2015 11:21 AM

Taken from helicopter, facing northeast, overview of the origin area.



Butte Incident

Photo 143

9/16/2015 11:21 AM

Taken from helicopter, facing north to northeast, looking through the advancing (head) of the fire towards the origin area.



Butte Incident

Photo 144

9/16/2015 11:21 AM

Taken from helicopter, facing north, overview of the origin area, from over the top of the last residence on Charamuga Ranch Road.



Butte Incident

Photo 145

9/16/2015 11:21 AM

Taken from helicopter, overview of residence at the end of Charamuga Ranch Road. Residence was just south of origin area where initial spot fires were observed.



Butte Incident

Photo 146

9/16/2015 11:21 AM

Taken from helicopter, facing northwest, overview of the origin area.



Butte Incident

Photo 147

9/16/2015 11:22 AM

Taken from helicopter, facing west, overview of the origin area, looking down powerline corridor.



Butte Incident

Photo 148

9/16/2015 11:22 AM

Taken from helicopter, facing west, overview of the origin area, looking down powerline corridor.



Butte Incident

Photo 149

9/16/2015 11:22 AM

Taken from helicopter, facing southwest, overview of the origin area.



Butte Incident

Photo 150

9/16/2015 11:22 AM

Taken from helicopter, facing southwest, overview of the origin area.



Butte Incident

Photo 151

9/16/2015 11:22 AM

Taken from helicopter, facing southwest, overview of the origin area.



Butte Incident

Photo 152

9/16/2015 11:22 AM

Taken from helicopter, facing southwest, overview of the origin area.



Butte Incident

Photo 153

9/16/2015 11:22 AM

Taken from helicopter, facing south, residence at the end of Charamuga Ranch Road.



Butte Incident

Photo 154

9/16/2015 11:23 AM

Taken from helicopter, facing south, overview of the origin area and residence at the end of Charamuga Ranch Road.



Butte Incident

Photo 155

9/16/2015 11:23 AM

Taken from helicopter, facing southeast, overview of the residence at the end of Charamuga Ranch Road.



Butte Incident

Photo 156

9/16/2015 11:23 AM

Taken from helicopter, facing southeast, view from above the origin area looking into the Mokelumne River drainage.



Butte Incident

Photo 157

9/16/2015 11:24 AM

Taken from helicopter, view of some of the spot fires south of the residence at the end of Charamuga Ranch Road.



Butte Incident

Photo 158

9/16/2015 11:24 AM

Taken from helicopter, view of fire area south of residence at the end of Charamuga Ranch Road.



Butte Incident

Photo 159

9/16/2015 11:25 AM

Taken from helicopter, facing north, view of fire area just east of Charamuga Ranch Road.



Butte Incident

Photo 160

9/16/2015 11:25 AM

Taken from helicopter, facing north, view of fire area just east of Charamuga Ranch Road.



Butte Incident

Photo 161

9/16/2015 11:25 AM

Taken from helicopter, facing north, view of fire area just east of Charamuga Ranch Road.



Butte Incident

Photo 162

9/16/2015 11:25 AM

Taken from helicopter, view of fire area east of Charamuga Ranch Road along the north rim of the Mokelumne River drainage.



Butte Incident

Photo 163

9/16/2015 11:25 AM

Taken from helicopter, view of fire area east of Charamuga Ranch Road along the north rim of the Mokelumne River drainage.



Butte Incident

Photo 164

9/16/2015 11:26 AM

Taken from helicopter, facing northwest, view of the origin area and residences along Charamuga Ranch Road.



Butte Incident

Photo 165

9/16/2015 11:26 AM

Taken from helicopter, facing northwest, view of the origin area and residences along Charamuga Ranch Road.



Butte Incident

Photo 166

9/16/2015 11:27 AM

Taken from helicopter, facing northwest, view of the origin area and residences along Charamuga Ranch Road.